



OUR TOWN HALL

PROJECT

Construction Progress
Photographs



Why we are doing this




Cumulative remaining life of assets from 2015 - 2045







The Story So Far: 2018 Heritage Assets

- Collectively weighing in at over 10 tonnes, 35 sculptures were moved to temporary homes.
- Almost 90 paintings were taken down, condition-checked, individually boxed and sent to storage.
- The entire collection of historic chairs and other pieces of furniture were removed to storage.
- The immense collection of plans, drawings and designs from the Sewer Plans Room are being documented, cleaned and archived.
- Thousands of glass plate negatives have been digitised for ease of access.



Protection to heritage finishes



New Mechanical and Electrical Services in Lower Ground Floor



Complex and substantial structural interventions



5.8 New stair S20 at level 5 Tuesday 26 July 2022



5.11 Steel beams installed on north side of Lloyd Street roof



5.12 New opening on the east side of room 04-024 Tuesday 15 March 2022



5.13 Brick infill installed above steel beams to opening in room 04-024



5.14 Removal of needles and props in progress in room 04-024 Wed 16 March



5.15 Removal of needles and props complete from new opening on the east side of room 04-024 Friday 18 March 2022



5.16 Overview of room 04-024 from south-east corner


Scaffold and Building Wrap



Removal of the Organ for off-site restoration



External stone repairs



5.88 Chimney CS21 viewed from south-east Tuesday 7 June 2022



5.87 Chimney CS21 viewed from south-west Tuesday 7 June 2022





5.89 Top of chimney CS21 viewed from south Tuesday 7 June 2022



5.90 Top of chimney CS21 viewed from north Tuesday 7 June 2022

Cleaning Great Hall ceilings



Roof restoration



5.110 Roof slopes WR19e Thursday 16 June 2022



5.109 Slate and battens removed from roof slope WR18 Thursday 16 June 2022



5.112 Slate and battens removed from top of roof WCR10 Thursday 16 June 2022




5.111 Chimneys CS34, CS09, CS08 and CS09 on north side of clock tower



5.2 Cooper Street temporary roof viewed from inside from south to north

Window restoration



5.40 Preparation for painting sash window frames underway in room 01-019



5.39 Sash window repairs and preparation for painting in room 01-019



5.46 View of leaded lights re-fitted in level 2 corridor from Princess St courtyard

Mosaic Restoration



5.36 Preparation of mosaic panel underway in workshop on level 1



Albert Square and the Public Realm




Figure 6 - Bollard installations on Southmill Street area



OUR
TOWN
HALL
PROJECT